

GOVERNMENT OF GUAM
DEPARTMENT OF PUBLIC HEALTH AND SOCIAL SERVICES
DIVISION OF ENVIRONMENTAL HEALTH

INSPECTION REPORT
LAUNDRY AND DRY CLEANING

1 OF 3 PAGES

INSPECTION	GRADE	Inspection Date	ESTABLISHMENT NAME	
Regular <input checked="" type="checkbox"/>	20/B	05/02/2018	MANONG'S MINIMART & LAUNDROMAT	
Follow-Up <input type="checkbox"/>		Inspection Time	OWNER/OPERATOR	
Complaint <input type="checkbox"/>		13:20	CLAW CORPORATION	
Investigation <input type="checkbox"/>		Time	LOCATION	
Other (Specify below) <input type="checkbox"/>		16:12	LOT 2410-8-3 #043 ROUTE 10 VETERANS MEMORIAL HIGHWAY, MANGILAO	
		Sanitary Permit #	ESTABLISHMENT TYPE	PERMIT CATEGORY STATUS (Circle One)
		170002520	PUBLIC LAUNDRY	Perm. /Temp. / <u>Current</u> /Expired

The following items identify violations found this day in the operations and facilities which must be corrected by the next inspection, or sooner as the Department indicates. Non-compliance may result in downgrading or permit suspension. To appeal, a written hearing request must be submitted before the indicated correction date.

A REGULAR INSPECTION WAS CONDUCTED TODAY. PREVIOUS INSPECTION DATED 10/17/2013 RESULTED IN A GRADE/RATING OF B/A. THE FOLLOWING WERE OBSERVED TODAY:

12. NO HOT WATER WAS FOUND IN HANDWASHING SINK NEAR WASHERS, IN MOP SINK, AND IN HANDWASHING SINK IN RESTROOM. AS PER PERSON-IN-CHARGE (PIC), THERE IS NOT HOT WATER THROUGHOUT THE WHOLE PUBLIC LAUNDRY FACILITY ONLY IN THE RETAIL SIDE. 4

A SUFFICIENT SUPPLY OF RUNNING COLD AND HOT WATER SHALL BE PROVIDED IN ALL WASHING MACHINES AND HANDWASHING SINKS WITH A MINIMUM TEMPERATURE OF 120°F AND MAXIMUM TEMPERATURE OF 140°F TO FACILITATE WITH THE PROPER WASHING OF CLOTHES/LINENS AND WITH HANDWASHING HYGIENE.

15. RESTROOM ON THE LEFT SIDE OF HANDWASHING SINK WAS FOUND INACCESSIBLE; MOP VR. DOOR TO RESTROOM WAS BLOCKED OFF WITH MANY UNNECESSARY ITEMS SUCH AS VACUUM, MOP BUCKET, USED CARDBOARD BOXES, EMPTY PLASTIC FABRIC SOFTENER CONTAINERS, AND A TRASH BAG; DEBRIS AND A BOX OF ARIEL DETERGENT SOAP WAS FOUND INSIDE RESTROOM. AS PER PIC, RESTROOM IS USED FOR STORAGE AND INSIDE THE DETERGENT BOX ARE PARTS FOR THE WASHING MACHINES. 4

TOILET FACILITIES SHALL BE ACCESSIBLE AT ALL TIMES ACCORDING TO THE RULES AND REGULATIONS GOVERNING LAUNDRY AND DRY CLEANING.

I have read and understand the above violation(s) and I am aware of the corrective measure to be taken.

*When any of the following items are cited above they shall be corrected within ten days of this inspection: (7), (8), (9), (10), (11), (12), (14), (15), (19), (20), (21), (24), (25), (27), (32), (33), (34), (35), and (37).

RECEIVED BY (Name and Title)

NELSON M. CONCEPCION

DEH INSPECTOR (Name and Title)

V. RAYMUNDO, EPITO I

Nelson M. Concepcion
STORE MGR.

GOVERNMENT OF GUAM
DEPARTMENT OF PUBLIC HEALTH AND SOCIAL SERVICES
DIVISION OF ENVIRONMENTAL HEALTH

INSPECTION REPORT
LAUNDRY AND DRY CLEANING

2 OF 3 PAGES

INSPECTION	GRADE	Inspection Date	ESTABLISHMENT NAME	
Regular <input checked="" type="checkbox"/>	20/B	05/02/2018	MANONG'S MINIMART & LAUNDROMAT	
Follow-Up <input type="checkbox"/>		Inspection Time	OWNER/OPERATOR	
Complaint <input type="checkbox"/>		13 Hr. 20 Min.	CLAN CORPORATION	
Investigation <input type="checkbox"/>		Travel Time	LOCATION	
Other (Specify below) <input type="checkbox"/>		16 Hr. 12 Min.	LOT 2416-3-3 #643 ROUTE 10 VETERANS MEMORIAL HIGHWAY, MANGILAO	
		Sanitary Permit #	ESTABLISHMENT TYPE	PERMIT CATEGORY STATUS (Circle One)
		170002520	PUBLIC LAUNDRY	Perm. /Temp. <u>Current</u> /Expired

The following items identify violations found this day in the operations and facilities which must be corrected by the next inspection, or sooner as the Department indicates. Non-compliance may result in downgrading or permit suspension. To appeal, a written hearing request must be submitted before the indicated correction date.

16. SEPARATE TOILET FOR BOTH SEXES NOT PROVIDED. AS PER PIC, THE RESTROOM ON THE LEFT SIDE OF MOP SINK IS USED FOR STORAGE. 2
- SEPARATE TOILET ROOMS FOR BOTH SEXES SHALL BE PROVIDED AS REQUIRED TO ENSURE BOTH MALE/FEMALE HAVE ADEQUATE RESTROOMS FOR USE ACCORDING TO THE RULES AND REGULATIONS GOVERNING LAUNDRY AND DRY CLEANING.
17. RESTROOM ON THE LEFT SIDE OF MOP SINK FOUND WITH A DISREPAIRED SELF-CLOSING DOOR AND WITHOUT VENTILATION. RESTROOM ON THE RIGHT SIDE OF MOP SINK WAS FOUND WITH A DISREPAIRED MESH SCREEN. 2
- TOILET ROOMS SHALL BE COMPLETELY ENCLOSED; SHALL HAVE TIGHT-FITTING AND SELF-CLOSING DOORS, WINDOWS OR SLIDING GLASS USED FOR VENTILATION; AND SHALL BE PROVIDED WITH AT LEAST NO. 16 MESH SCREEN TO PREVENT HARBOURAGE OF PESTS.
18. NO HANDWASHING SIGN POSTED IN RESTROOM SINK. COS.
- *CORRECTIVE ACTION: PIC, PROVIDED HANDWASHING SIGN.
- A HANDWASHING NOTICE SHALL BE POSTED IN EACH TOILET ROOM TO ENSURE THE PROPER AREA FOR HANDWASHING.
20. NO PAPER TOWEL AND HANDSOAP WERE PROVIDED IN HAND-WASHING SINK NEAR WASHER AND HANDWASHING IN ~~RESTROOM~~ ^{SINK} ~~RESTROOM~~ ^{V.R.} COS
- EACH HANDWASHING ^{SINK} SHALL BE PROVIDED WITH PAPER TOWEL AND HANDSOAP TO FACILITATE WITH PROPER HANDWASHING HYGIENE.

I have read and understand the above violation(s) and I am aware of the corrective measure to be taken.

*When any of the following items are cited above they shall be corrected within ten days of this inspection: (7), (8), (9), (10), (11), (12), (14), (15), (19), (20), (21), (24), (25), (27), (32), (33), (34), (35), and (37).

RECEIVED BY (Name and Title)

NELSON M. CONCEPCION

DEH INSPECTOR (Name and Title)

V. RAYMUNDO, EPHD I

Nelson M. Concepcion
STORE MGR

GOVERNMENT OF GUAM
DEPARTMENT OF PUBLIC HEALTH AND SOCIAL SERVICES
DIVISION OF ENVIRONMENTAL HEALTH

INSPECTION REPORT
LAUNDRY AND DRY CLEANING

3 OF 3 PAGES

INSPECTION	GRADE	Inspection Date	ESTABLISHMENT NAME
Regular <input checked="" type="checkbox"/>	20/B	05/02/2018	MANONG'S MINIMART & LAUNDRY
Follow-Up <input type="checkbox"/>		Inspection Time	OWNER/OPERATOR
Complaint <input type="checkbox"/>		13 Hr. 20 Min.	CLAN CORPORATION
Investigation <input type="checkbox"/>		OUT Time	LOCATION
Other (Specify below) <input type="checkbox"/>		16 Hr. 12 Min.	LOT 2416-3-3 # 643 ROUTE 10 VETERANS MEMORIAL HIGHWAY, MANGILAO
		Sanitary Permit #	ESTABLISHMENT TYPE
		170002526	PUBLIC LAUNDRY
			PERMIT CATEGORY STATUS (Circle One)
			Perm. /Temp. /Current /Expired

The following items identify violations found this day in the operations and facilities which must be corrected by the next inspection, or sooner as the Department indicates. Non-compliance may result in downgrading or permit suspension. To appeal, a written hearing request must be submitted before the indicated correction date.

- * CORRECTIVE ACTION: PIC PROVIDED PAPER TOWEL AND HANDSAP FOR BOTH HANDWASHING SINK.
30. MULTIPLE UNNECESSARY ARTICLES/TRASH OUTSIDE BACK AREA OF ESTABLISHMENT.
PREMISES SHALL BE FREE OF UNNECESSARY ARTICLES TO MAINTAIN THE SANITARY CONDITION OF THE FACILITY AND TO PREVENT HARBORAGE OF PESTS. 2 06/01/2018
8. HANDWASHING SINK NEAR WASHER WAS FOUND LEAKING.
HANDWASHING SINK SHALL BE MAINTAINED AND IN A GOOD STATE OF REPAIR TO FACILITATE WITH PROPER HANDWASHING HYGIENE. 6 05/14/2018
- PHOTOS WERE TAKEN.
REMOVED PLACARD "A" NO. 01401
POSTED PLACARD "B" NO. 01031.
ISSUED RE-INSPECTION REQUEST FORM.
DISCUSSED THIS REPORT WITH NELSON CONCEPCION, OWNER/STORE MANAGER

I have read and understand the above violation(s) and I am aware of the corrective measure to be taken.

*When any of the following items are cited above they shall be corrected within ten days of this inspection: (7), (8), (9), (10), (11), (12), (14), (15), (19), (20), (21), (24), (25), (27), (32), (33), (34), (35), and (37).

RECEIVED BY (Name and Title)

NELSON M. CONCEPCION

DEH INSPECTOR (Name and Title)

V. RAMMUNDO, EPITO I

Nelson M. Concepcion
STORE MGR

300-9570